

# INFORMATION NOTE



N° 023/20

**! UPDATE !**

Update of Information Note 023/20 dated 2020-03-09:

New 'Intended start of delivery' dates highlighted in blue type.

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

**Introduction of new reel cover tape affecting SOT89, SOT223 and TSSOP10 package products packed at Infineon Technologies (Wuxi) Co. Ltd., Wuxi, China.**

Infineon Technologies AG

Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0

Chairman of the Supervisory Board: Dr. Eckart Sünner

Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider

Registered Office: Neubiberg

Commercial Register: München HRB 126492

# INFORMATION NOTE



N° 023/20

**! UPDATE !**

**Introduction of new reel cover tape affecting SOT89, SOT223 and TSSOP10 package products packed at Infineon Technologies (Wuxi) Co. Ltd., Wuxi, China.**

► **Products affected:** Please refer to attached affected product list 1\_cip02320.xlsx

► **Detailed Change Information:**

**Subject:** Introduction of new reel cover tape affecting SOT89, SOT223 and TSSOP10 package products packed at Infineon Technologies (Wuxi) Co. Ltd., Wuxi, China.

**Reason:** Package packing standardization

**Description:**  
Reel cover tape

Old



(Picture taken from SOT89)

■ Milky white

New



(Picture taken from SOT89)

■ Transparent

► **Product Identification:** Internal traceability ensured via lot number & date code

► **Impact of Change:** No change of Form, Fit & Function of product. Cover tape change only.

► **Attachments:**  
Affected product list : 1\_cip02320.xlsx  
Customer information package : 3\_cip02320.pdf

► **Intended start of delivery:**  
~~05-May-2020~~  
**SOT89 05-May-2020**  
**TSSOP10 24-Jul-2020**  
**SOT223 06-Nov-2020**

If you have any questions, please do not hesitate to contact your local Sales office.

**INF 023/20**

Introduction of new reel cover tape affecting SOT89, SOT223 and TSSOP10 package products packed at Infineon Technologies (Wuxi) Co. Ltd., Wuxi, China.



| Sales name      | SP number   | OPN               | Package |
|-----------------|-------------|-------------------|---------|
| BAW 78D H6327   | SP001125530 | BAW78DH6327XTSA1  | SOT89   |
| BAW 79D H6327   | SP001125532 | BAW79DH6327XTSA1  | SOT89   |
| BCP 49 H6327    | SP000747598 | BCP49H6327XTSA1   | SOT223  |
| BCP 49 H6359    | SP000748082 | BCP49H6359XTMA1   | SOT223  |
| BCP 49 H6419    | SP000748086 | BCP49H6419XTMA1   | SOT223  |
| BCP 51 H6327    | SP000748088 | BCP51H6327XTSA1   | SOT223  |
| BCP 51-16 H6327 | SP000748090 | BCP5116H6327XTSA1 | SOT223  |
| BCP 51-16 H6433 | SP000748092 | BCP5116H6433XTMA1 | SOT223  |
| BCP 52-16 H6327 | SP000748096 | BCP5216H6327XTSA1 | SOT223  |
| BCP 53-10 H6327 | SP000748122 | BCP5310H6327XTSA1 | SOT223  |
| BCP 53-16 H6327 | SP000748124 | BCP5316H6327XTSA1 | SOT223  |
| BCP 53-16 H6433 | SP000748126 | BCP5316H6433XTMA1 | SOT223  |
| BCP 54 H6327    | SP000748128 | BCP54H6327XTSA1   | SOT223  |
| BCP 54-16 H6327 | SP000748130 | BCP5416H6327XTSA1 | SOT223  |
| BCP 54-16 H6433 | SP000748132 | BCP5416H6433XTMA1 | SOT223  |
| BCP 55 H6327    | SP000748362 | BCP55H6327XTSA1   | SOT223  |
| BCP 55-16 H6327 | SP000748364 | BCP5516H6327XTSA1 | SOT223  |
| BCP 56-10 H6327 | SP000748366 | BCP5610H6327XTSA1 | SOT223  |
| BCP 56-16 H6327 | SP000748370 | BCP5616H6327XTSA1 | SOT223  |
| BCP 69-25 H6327 | SP000748374 | BCP6925H6327XTSA1 | SOT223  |
| BCV 28 H6327    | SP001125534 | BCV28H6327XTSA1   | SOT89   |
| BCV 29 H6327    | SP001125300 | BCV29H6327XTSA1   | SOT89   |
| BCV 48 H6327    | SP001125544 | BCV48H6327XTSA1   | SOT89   |
| BCV 49 H6327    | SP001125332 | BCV49H6327XTSA1   | SOT89   |
| BCX 51 H6327    | SP001125334 | BCX51H6327XTSA1   | SOT89   |
| BCX 51-16 H6327 | SP001125336 | BCX5116H6327XTSA1 | SOT89   |
| BCX 51-16 H6433 | SP001125338 | BCX5116H6433XTMA1 | SOT89   |
| BCX 52 H6327    | SP001125340 | BCX52H6327XTSA1   | SOT89   |
| BCX 52-16 H6327 | SP001125342 | BCX5216H6327XTSA1 | SOT89   |
| BCX 52-16 H6433 | SP001125344 | BCX5216H6433XTMA1 | SOT89   |
| BCX 53 H6327    | SP001125346 | BCX53H6327XTSA1   | SOT89   |
| BCX 53-10 H6327 | SP001125348 | BCX5310H6327XTSA1 | SOT89   |
| BCX 53-16 H6327 | SP001125456 | BCX5316H6327XTSA1 | SOT89   |
| BCX 53-16 H6433 | SP001125462 | BCX5316H6433XTMA1 | SOT89   |
| BCX 54-16 H6327 | SP001125468 | BCX5416H6327XTSA1 | SOT89   |
| BCX 55 H6327    | SP001125470 | BCX55H6327XTSA1   | SOT89   |

|                 |             |                   |        |
|-----------------|-------------|-------------------|--------|
| BCX 55-16 H6327 | SP001125472 | BCX5516H6327XTSA1 | SOT89  |
| BCX 55-16 H6433 | SP001125474 | BCX5516H6433XTMA1 | SOT89  |
| BCX 56 H6327    | SP001125476 | BCX56H6327XTSA1   | SOT89  |
| BCX 56 H6359    | SP001125478 | BCX56H6359XTMA1   | SOT89  |
| BCX 56-10 H6327 | SP001125480 | BCX5610H6327XTSA1 | SOT89  |
| BCX 56-16 H6327 | SP001125482 | BCX5616H6327XTSA1 | SOT89  |
| BCX 56-16 H6433 | SP001125484 | BCX5616H6433XTMA1 | SOT89  |
| BCX 68-10 H6327 | SP001125486 | BCX6810H6327XTSA1 | SOT89  |
| BCX 68-16 H6327 | SP001125488 | BCX6816H6327XTSA1 | SOT89  |
| BCX 68-25 H6327 | SP001125490 | BCX6825H6327XTSA1 | SOT89  |
| BCX 69-10 H6327 | SP001125298 | BCX6910H6327XTSA1 | SOT89  |
| BCX 69-16 H6327 | SP001125264 | BCX6916H6327XTSA1 | SOT89  |
| BCX 69-25 H6327 | SP001125266 | BCX6925H6327XTSA1 | SOT89  |
| BDP 947 H6327   | SP000748376 | BDP947H6327XTSA1  | SOT223 |
| BDP 948 H6327   | SP000748378 | BDP948H6327XTSA1  | SOT223 |
| BDP 948 H6433   | SP000748380 | BDP948H6433XTMA1  | SOT223 |
| BDP 949 H6327   | SP000748382 | BDP949H6327XTSA1  | SOT223 |
| BDP 950 H6327   | SP000748522 | BDP950H6327XTSA1  | SOT223 |
| BDP 953 H6327   | SP000748526 | BDP953H6327XTSA1  | SOT223 |
| BDP 954 H6327   | SP000748528 | BDP954H6327XTSA1  | SOT223 |
| BFN 18 H6327    | SP001125290 | BFN18H6327XTSA1   | SOT89  |
| BFN 19 H6327    | SP001125292 | BFN19H6327XTSA1   | SOT89  |
| BFN 38 H6327    | SP000748530 | BFN38H6327XTSA1   | SOT223 |
| BFN 39 H6327    | SP000748532 | BFN39H6327XTSA1   | SOT223 |
| BFQ 19S H6327   | SP001125294 | BFQ19SH6327XTSA1  | SOT89  |
| BFQ 19S H6359   | SP001125296 | BFQ19SH6359XTMA1  | SOT89  |
| BFQ 790 H6327   | SP001078878 | BFQ790H6327XTSA1  | SOT89  |
| BSP 50 H6327    | SP000748534 | BSP50H6327XTSA1   | SOT223 |
| BSP 51 H6327    | SP000748536 | BSP51H6327XTSA1   | SOT223 |
| BSP 52 H6327    | SP000748886 | BSP52H6327XTSA1   | SOT223 |
| BSP 60 H6327    | SP000749082 | BSP60H6327XTSA1   | SOT223 |
| BSP 61 H6327    | SP000749562 | BSP61H6327XTSA1   | SOT223 |
| BSP 62 H6327    | SP000749564 | BSP62H6327XTSA1   | SOT223 |
| BSP125 H6327    | SP001058576 | BSP125H6327XTSA1  | SOT223 |
| BSP125 H6433    | SP001058578 | BSP125H6433XTMA1  | SOT223 |
| BSP129 H6327    | SP001058580 | BSP129H6327XTSA1  | SOT223 |
| BSP129 H6906    | SP001058586 | BSP129H6906XTSA1  | SOT223 |
| BSP135 H6327    | SP001058812 | BSP135H6327XTSA1  | SOT223 |
| BSP135 H6433    | SP001058592 | BSP135H6433XTMA1  | SOT223 |
| BSP135 H6906    | SP001058594 | BSP135H6906XTSA1  | SOT223 |
| BSP149 H6327    | SP001058818 | BSP149H6327XTSA1  | SOT223 |
| BSP149 H6906    | SP001058604 | BSP149H6906XTSA1  | SOT223 |
| BSP170P H6327   | SP001058608 | BSP170PH6327XTSA1 | SOT223 |
| BSP171P H6327   | SP001058824 | BSP171PH6327XTSA1 | SOT223 |

|               |             |                   |        |
|---------------|-------------|-------------------|--------|
| BSP171P H6919 | SP001058616 | BSP171PH6919XTSA1 | SOT223 |
| BSP179 H6327  | SP001212770 | BSP179H6327XTSA1  | SOT223 |
| BSP295 H6327  | SP001058618 | BSP295H6327XTSA1  | SOT223 |
| BSP296N H6327 | SP001059330 | BSP296NH6327XTSA1 | SOT223 |
| BSP296N H6433 | SP001098610 | BSP296NH6433XTMA1 | SOT223 |
| BSP297 H6327  | SP001058622 | BSP297H6327XTSA1  | SOT223 |
| BSP298 H6327  | SP001058626 | BSP298H6327XUSA1  | SOT223 |
| BSP299 H6327  | SP001058628 | BSP299H6327XUSA1  | SOT223 |
| BSP300 H6327  | SP001058720 | BSP300H6327XUSA1  | SOT223 |
| BSP315P H6327 | SP001058830 | BSP315PH6327XTSA1 | SOT223 |
| BSP316P H6327 | SP001058754 | BSP316PH6327XTSA1 | SOT223 |
| BSP317P H6327 | SP001058758 | BSP317PH6327XTSA1 | SOT223 |
| BSP318S H6327 | SP001058838 | BSP318SH6327XTSA1 | SOT223 |
| BSP320S H6327 | SP001058768 | BSP320SH6327XTSA1 | SOT223 |
| BSP320S H6433 | SP001058772 | BSP320SH6433XTMA1 | SOT223 |
| BSP321P H6327 | SP001058782 | BSP321PH6327XTSA1 | SOT223 |
| BSP322P H6327 | SP001058784 | BSP322PH6327XTSA1 | SOT223 |
| BSP324 H6327  | SP001058786 | BSP324H6327XTSA1  | SOT223 |
| BSP372N H6327 | SP001059326 | BSP372NH6327XTSA1 | SOT223 |
| BSP373N H6327 | SP001059328 | BSP373NH6327XTSA1 | SOT223 |
| BSP612P H6327 | SP001098612 | BSP612PH6327XTSA1 | SOT223 |
| BSP613P H6327 | SP001058788 | BSP613PH6327XTSA1 | SOT223 |
| BSP716N H6327 | SP001087514 | BSP716NH6327XTSA1 | SOT223 |
| BSP88 H6327   | SP001058790 | BSP88H6327XTSA1   | SOT223 |
| BSP89 H6327   | SP001058794 | BSP89H6327XTSA1   | SOT223 |
| BSP92P H6327  | SP001058796 | BSP92PH6327XTSA1  | SOT223 |
| BSS192P H6327 | SP001047642 | BSS192PH6327FTSA1 | SOT89  |
| BSS192P H6327 | SP001195030 | BSS192PH6327XTSA1 | SOT89  |
| BSS225 H6327  | SP001047644 | BSS225H6327FTSA1  | SOT89  |
| BSS225 H6327  | SP001195032 | BSS225H6327XTSA1  | SOT89  |
| BSS606N H6327 | SP000691152 | BSS606NH6327XTSA1 | SOT89  |
| BSS87 H6327   | SP001047646 | BSS87H6327FTSA1   | SOT89  |
| BSS87 H6327   | SP001195034 | BSS87H6327XTSA1   | SOT89  |
| ISP12DP06NM   | SP004987268 | ISP12DP06NMXTSA1  | SOT223 |
| ISP15EP15LM   | SP005343899 | ISP15EP15LMXTSA1  | SOT223 |
| ISP1XEP10LM   | SP005343907 | ISP1XEP10LMXTSA1  | SOT223 |
| ISP25DP06LM   | SP004987270 | ISP25DP06LMXTSA1  | SOT223 |
| ISP25DP06NM   | SP004987272 | ISP25DP06NMXTSA1  | SOT223 |
| ISP2XDP10LM   | SP005343903 | ISP2XDP10LMXTSA1  | SOT223 |
| ISP2XEP10LM   | SP005343889 | ISP2XEP10LMXTSA1  | SOT223 |
| ISP650P06NM   | SP004987266 | ISP650P06NMXTSA1  | SOT223 |
| ISP75DP06LM   | SP004987274 | ISP75DP06LMXTSA1  | SOT223 |
| PZTA 14 H6327 | SP000749566 | PZTA14H6327XTSA1  | SOT223 |
| PZTA 42 H6327 | SP000749568 | PZTA42H6327XTSA1  | SOT223 |

|          |             |               |             |
|----------|-------------|---------------|-------------|
| TDA5103A | SP000305485 | TDA5103AHTMA1 | PG-TSSOP-10 |
| TDA5150  | SP000300415 | TDA5150HTMA1  | PG-TSSOP-10 |
| TDA7100  | SP000296466 | TDA7100HTMA1  | PG-TSSOP-10 |
| TDA7110F | SP000611108 | TDA7110FHTMA1 | PG-TSSOP-10 |
| TDA7116F | SP000611114 | TDA7116FHTMA1 | PG-TSSOP-10 |
| TDK5100F | SP000014745 | TDK5100FHTMA1 | PG-TSSOP-10 |
| TDK5101F | SP000014744 | TDK5101FHTMA1 | PG-TSSOP-10 |
| TDK5110F | SP000056180 | TDK5110FHTMA1 | PG-TSSOP-10 |
| TDK5111F | SP000056181 | TDK5111FHTMA1 | PG-TSSOP-10 |
| TDK5116F | SP000056182 | TDK5116FHTMA1 | PG-TSSOP-10 |
| TX98-3   | SP000743718 | TX983HTMA1    | PG-TSSOP-10 |
| TX98-4   | SP000743714 | TX984HTMA1    | PG-TSSOP-10 |