



To: Distributor Partners

Issue date: September 1, 2021
PTN No.: 102100C

Kenichi Fukumoto
General manager
LSI Business Unit

ROHM Co., Ltd.

Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledges the obligation to promptly inform our customers of the intent to exit products to enable out customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

ROHM sincerely requires acknowledgment of receipt of this notification within 30 days of the date of this notice. Lack of acknowledgment of this notice within 30 days constitutes acceptance of the change. Your understanding and cooperation would be highly appreciated.

| Product category | Affected part number(s) | Suggested replacement product |
|--|-----------------------------------|-------------------------------|
| LSI | Please see attached list of parts | — |
| <u>Reason for discontinuance</u> Due to the decrease of production volume, it has become difficult to continue the business in the future. So we will discontinue these products. | | |
| <u>Product discontinuance date</u> December 1.2022 | | |
| <u>Order after discontinuance</u> Regarding the required number of supplies after discontinuation, If you present it by October 01, 2022, we plan to manufacture it all at once before it is discontinued. In addition, please collect this required number in a lump sum. | | |

| Dev. | ROHM Internal P/N |
|--------------|--------------------------|
| Standard LSI | BU2373FV-E2 |
| Standard LSI | BU8903GU-E2 |
| Standard LSI | BU1570KN-E2 |
| Standard LSI | BU9346K-E2 |
| Standard LSI | BU9428KV-E2 |
| Standard LSI | BH7616HFV-TR |
| Standard LSI | BD3485FS-E2 |
| Standard LSI | BU1571KN-E2 |
| Standard LSI | BU8899GU-E2 |
| Standard LSI | BD3489FS-E2 |
| Standard LSI | BD3482FS-E2 |
| Standard LSI | BU3073HFV-TR |
| Standard LSI | BU1572GUW-E2 |
| Standard LSI | BU2363FV-E2 |
| Standard LSI | BR93A56F-WME2 |
| Standard LSI | BD3826FS-E2 |
| Standard LSI | BU6569GVW-E2 |
| Standard LSI | BU7328HFV-TR |
| Standard LSI | BU1569GVW-E2 |
| Standard LSI | BU3056FV-E2 |
| Standard LSI | BD5427EFS-E2 |
| Standard LSI | BH76909GU-E2 |
| Standard LSI | BD4859FVE-TR |
| Standard LSI | BU6520KV-E2 |
| Standard LSI | BD3825FS-E2 |
| Standard LSI | BD3402KS2 |
| Standard LSI | BU94705KV-E2 |
| Standard LSI | BU1563GV-E2 |
| Standard LSI | BD4851FVE-TR |
| Standard LSI | BU94702KV-E2 |
| Standard LSI | BD7630FV-E2 |
| Standard LSI | BU3071HFV-TR |
| Standard LSI | BD4849FVE-TR |
| Standard LSI | BU7343HFV-TR |
| Standard LSI | BU7980KVT-E2 |
| Standard LSI | BD5427MUV-E2 |
| Standard LSI | BD3486FS-E2 |
| Standard LSI | BD3487FS-E2 |
| Standard LSI | BU7858KN-E2 |
| Standard LSI | BD3822FS-E2 |
| Standard LSI | BU7843AGU-E2 |
| Standard LSI | BU2358FV-E2 |
| Standard LSI | BR93L76FJ-WE2 |
| Standard LSI | BH76706GU-E2 |
| Standard LSI | BD3488FS-E2 |

| | |
|----------------------|---------------|
| Standard LSI | BU9348K |
| Standard LSI | BD3484FS-E2 |
| Standard LSI | BD3481FS-E2 |
| Standard LSI | BU9486KV-E2 |
| AFELSI | BD3893FV-E2 |
| AFELSI | BH1411MUV-E2 |
| AFELSI | BH1425GWL-E2 |
| AFELSI | BH1426GWL-E2 |
| AFELSI | BH1428MUV-E2 |
| AFELSI | BU6375FV-E2 |
| AFELSI | BU7615AMUV-E2 |
| AFELSI | BU7625MUV-E2 |
| AFELSI | BU7805GLU-E2 |
| AFELSI | BU7814KN-E2 |
| AFELSI | BU7844GU-E2 |
| AFELSI | BU7966GUW-E2 |
| AFELSI | BH1411FV-E2 |
| AFELSI | BU7625GUW-E2 |
| AFELSI | BU7813KN-E2 |
| Motor LSI | BU9967KN-E2 |
| Motor LSI | BD7915FP-E2 |
| Motor LSI | BD7776RFS-E2 |
| Motor LSI | BD6886GUL-E2 |
| Motor LSI | BD6884GUW-E2 |
| Motor LSI | BD6874GSW-E2 |
| Motor LSI | BD6874GLS-E2 |
| Motor LSI | BD6794EFV-E2 |
| Motor LSI | BD6643KN-E2 |
| Motor LSI | BD6640KUT-E2 |
| Motor LSI | BA6896FP-E2 |
| Motor LSI | BA6665FM-E2 |
| Motor LSI | BA6897FP-E2 |
| Motor LSI | BA5965FV-E2 |
| Motor LSI | BA5891FM-E2 |
| Motor LSI | BA5891FM-DE2 |
| Motor LSI | BA5837FM-E2 |
| Motor LSI | BD6758MWV-E2 |
| Motor LSI | BD6201FS-E2 |
| Power Management LSI | BA5916FP-YE2 |
| Power Management LSI | BD3500FVM-TR |
| Power Management LSI | BD3501FVM-TR |
| Power Management LSI | BD3610EFV-E2 |
| Power Management LSI | BD4900FM-E2 |
| Power Management LSI | BD4901FM-E2 |
| Power Management LSI | BD4903FM-E2 |
| Power Management LSI | BD6023AGU-E2 |

Power Management LSI BD6025GU-E2
Power Management LSI BD6155FVM-TR
Power Management LSI BD8130KN-E2
Power Management LSI BD8154EFV-E2
Power Management LSI BD8602FV-E2
Power Management LSI BD8611EFV-E2
Power Management LSI BD8620EFV-E2
Power Management LSI BD9142MUV-E2
Power Management LSI BD9749MWV-E2
Power Management LSI BD9750BFV-E2
Power Management LSI BD9751FV-E2
Power Management LSI BD9753FV-FE2
Power Management LSI BD9833KV-E2
Power Management LSI BH6038KN-E2
Power Management LSI BH6046KN-E2
Power Management LSI BH6048KN-E2
Power Management LSI BH6053GU-E2
Power Management LSI BH6054GU-E2
Power Management LSI BH6069GU-E2
Power Management LSI BH6317GLU-E2
Power Management LSI BH6941KN-E2
Power Management LSI BH6942KN-E2
Power Management LSI BH6943KN-E2
Power Management LSI BU7875GLS-E2
Power Management LSI BU8770AFV-E2