



Not Recommended for New Design: HN Series Relays & Sockets

NRFND.PG0003.05.14.2020

05.14.2020

About This Notice:	The Panasonic HN Series Relays and Accessories (Relay Terminal Sockets) are Not Recommended For New Designs due to possible plans for discontinuation in the future.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See Attached. There are no direct replacements.
Datasheet(s):	See Attached.
Notes:	

Panasonic NRFND.PG0003.05.14.2020 Affected Parts

Part Number

AHN11012
AHN11024
AHN110X0
AHN110X1
AHN110Y0
AHN110Y2
AHN11112
AHN11124
AHN111X0
AHN111X1
AHN111Y0
AHN111Y2
AHN12005
AHN12006
AHN12012
AHN12024
AHN12048
AHN120X0
AHN120X1
AHN12105
AHN12106
AHN12112
AHN12124
AHN12148
AHN121X0
AHN121X1
AHN12205
AHN12206
AHN12212
AHN12224
AHN12248
AHN122X0
AHN122X1
AHN12305
AHN12306
AHN12312
AHN12324
AHN12348
AHN123X0
AHN123X1
AHN21012
AHN21012N
AHN21024
AHN21024N
AHN210X0
AHN210X0N

AHN210X1
AHN210X1N
AHN210Y0
AHN210Y0N
AHN210Y2
AHN210Y2N
AHN21112
AHN21112N
AHN21124
AHN21124N
AHN211X0N
AHN211X1
AHN211X1N
AHN211Y0
AHN211Y0N
AHN211Y2
AHN211Y2N
AHN22005
AHN22005N
AHN22006
AHN22006N
AHN22012
AHN22012N
AHN22024N
AHN22048
AHN22048N
AHN220X0
AHN220X0N
AHN220X1
AHN220X1N
AHN22105
AHN22105N
AHN22106
AHN22106N
AHN22112
AHN22112N
AHN22124
AHN22124N
AHN22148
AHN22148N
AHN221X0
AHN221X0N
AHN221X1
AHN221X1N
AHN22205N
AHN22206
AHN22206N
AHN22212N
AHN22224N

AHN22248
AHN22248N
AHN222X0
AHN222X0N
AHN222X1
AHN222X1N
AHN22305
AHN22305N
AHN22306
AHN22306N
AHN22312
AHN22312N
AHN22324
AHN22324N
AHN22348
AHN22348N
AHN223X0
AHN223X0N
AHN223X1
AHN223X1N
AHN35012
AHN35024
AHN350X0
AHN350X1
AHN350Y0
AHN350Y2
AHN36005
AHN36006
AHN36012
AHN36024
AHN36048
AHN360X0
AHN360X1
AHNA13
AHNA23
AHNA11K
AHNA11
AHNA21K
AHNA21