



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000999

DATE: 21-Jul-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS1922F#	N/A	21-Jul-2021	17-Jan-2022	Part can no longer be manufactured
Discontinuance	DG308AC/D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DG308AC/D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS1077LU-60+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1077LU-60+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1110S-75+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1110S-75+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1350WP-100IND+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1350WP-100IND+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1672-33+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1706EPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS1706EPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS1815-20+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS1818-20+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS1818-20+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS2741N+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	DS9105-SET#	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	ICL7611ACPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7611ACPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7622BCPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7622BCPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7211IQH+D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	ICM7211IQH+D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	ICM7242MJA	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX1022BETX+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1022BETX+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX11324ATJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11324ATJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1157AEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1157AEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1187AEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1187AEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1187BEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1187BEUI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX122BENG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX122BENG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1243AEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1243AEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1273CUA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1273CUA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1297BEEG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1297BEEG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX13038ATX+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX13038ATX+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1518BETJ+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX154ACAG+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX15511IGTL+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15511IGTL+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15567ETG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15567ETG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16055JAUB+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX16055JAUB+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX161BCPI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX161BCPI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16998BAUA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX17016ETL+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX17108ETI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17108ETI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17126BETM+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17126BETM+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17126BETM+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17126BETM+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX172BENG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX172BENG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17482GTL+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17528GTJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17528GTJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX184BCNG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX184BCNG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1865TEEP+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX1865TEEP+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX1902EAI+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX1902EAI+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX19192ETI+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX201EPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX201EPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2039ETP+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2039ETP+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX268ACWG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX268ACWG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX270EPP+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX296CWE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX296CWE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3073EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3073EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3073EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3073EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3076EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3076EAPD+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3130EAI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3130EAI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31912AUI+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX324CUA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX3371ELT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX3371ELT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX339EPE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX339EPE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3456EEUD+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX354MJE	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX397CPI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX397CPI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4008EUT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX412BEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX412BEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4431ESA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4431ESA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4519CEE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX4563CEE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4563CEE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4571CAI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4571CAI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4665CPE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX4722EBL+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4722EBL+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4800ACXZ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4864LELT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX5131BEEE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX535AEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX535AEPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX537BEPE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX537BEPE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5385EZT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX545BCSD+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX5909EEE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5909EEE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5929AHEEG+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX5933FESA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5933FESA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6023EBT50+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6332UR20D3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6332UR20D3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6333UR20D3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6333UR20D3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6339MUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX6339MUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6342MUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6342MUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6342MUT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6342MUT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6345ZUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6345ZUT+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6345ZUT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6345ZUT+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6361LUT44+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6361LUT44+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6363PUT44+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6363PUT44+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6365LKA46+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6365LKA46+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6377XR24+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6377XR24+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6377XR24+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6377XR24+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6379UR44+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6379UR44+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6386XS29D1+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6390XS26D7+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6392KA23+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6392KA23+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6421XS16+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6421XS16+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6425UK28+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6425UK28+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6456UT29L+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6456UT29L+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6456UT29L+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6456UT29L+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6466XR46+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6466XR46+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6575HZUT+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX6575HZUT+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6575HZUT+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6575HZUT+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6703MKA+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6709CUB+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6718AUKRVD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6736XKRVD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6737XKSFD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6737XKSFD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6738XKLD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6738XKLD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6738XKLD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6738XKLD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6740XKWGD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6740XKWGD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6752KA31+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6752KA31+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6762TALTD3+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6762TALTD3+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6792TPLD2+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6792TPLD2+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6845UKD0+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6845UKD0+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK16D3L+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK16D3L+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK16D3L+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6866UK16D3L+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6867UK17D3S+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6867UK17D3S+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6888CETE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6888CETE+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6975ATL+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX6975ATL+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX704REPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX706ATEUA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX706ATEUA+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX706TC/D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX708RCPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX708RCPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX709SCPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX709SCPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX7129CQH+D	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7129CQH+D	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7705CPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX7705CPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX770CPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX770CPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX770EPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX770EPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX797MJE	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX804RCSA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX804RCSA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX815LEPA+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8213BEPE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8213BEPE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8555AEUB+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8570EUT+TC70	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8570EUT+TC70	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8599ETE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8599ETE+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8716ETG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8716ETG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8726EUE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8726EUE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8775ETJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8775ETJ+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8775ETJ+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8775ETJ+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8785AETI+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8785AETI+T	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Aug-2020

Discontinuance	MAX883C/D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX883C/D	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8857AETL+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8867EUK29+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8867EUK29+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8867EUK29+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8867EUK29+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8883EUTA5+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8883EUTA5+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8999YEXT18+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX8999YEXT18+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX9324EUP+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX9384EWP+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX9700CEUB+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9700CEUB+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9719CETE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9719CETE+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX972CPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX972CPA+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7545LN+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7547LEWG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7547LEWG+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7576JN+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7576JN+	N/A	19-Oct-2020	17-Jan-2021	Part can no longer be manufactured
Discontinuance	MXD1813UR46+	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured
Discontinuance	MXD1813UR46+T	N/A	16-Jul-2021	12-Jan-2022	Part can no longer be manufactured