

PRODUCT DISCONTINUATION



PD_025_16

Reason: Low volume production

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
IPB80N06S2-05	SP000218877	IPB80N06S205ATMA1	PG-TO263-3	IPB100N06S2-05	SP001067896	IPB100N06S205ATMA4	PG-TO263-3
IPB80N06S2-05	SP001067936		PG-TO263-3	IPB100N06S2-05	SP001067896	IPB100N06S205ATMA4	PG-TO263-3
IPB80N06S2L-05	SP000219004	IPB80N06S2L05ATMA1	PG-TO263-3	IPB100N06S2L-05	SP001067944	IPB100N06S2L05ATMA2	PG-TO263-3
IPB80N06S2L-05	SP001067946		PG-TO263-3	IPB100N06S2L-05	SP001067944	IPB100N06S2L05ATMA2	PG-TO263-3
IPP80N04S2-04	SP000219054	IPP80N04S204AKSA1	PG-TO220-3	AUIRF1404	SP001522606	AUIRF1404	PG-TO220-3
IPP80N06S2-05	SP000218873	IPP80N06S205AKSA1	PG-TO220-3	AUIRF1405	SP001519124	AUIRF1405	PG-TO220-3
IPP80N06S2-05	SP001067940		PG-TO220-3	AUIRF1405	SP001519124	AUIRF1405	PG-TO220-3

■ Last order:	2016-10-01
■ Last delivery:	2017-04-01

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!