
Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: June 26th, 2019
RE: Discontinuation of Radial Leaded Inductors: LH Series
REF NO.: UTY-DN19-05D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued **9/26/2019** for all TAIYO YUDEN (U.S.A) Inc. distributors. Please note that any last time buys must be made on or before **9/26/2019**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Please reference **Appendix_UTY-DN19-05D_Part List** for complete list of discontinued parts and suggested alternatives.

***Please note the suggested alternative part numbers are not direct, drop-in replacements. Therefore, the part number spec/datasheet should be consulted for comparison details.**

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department

LHLZ06TB101K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB101KS	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB101K-FW	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB102J	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB150K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB151K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB1R0M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB1R5M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB220K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB221K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB221KB	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB2R2M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB330K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB331K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB331KS	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB331KSS	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB391K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB3R3M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB470K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB471K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB4R7M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB680K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB681K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ06TB6R8M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ08NB9R0M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ08TB152J	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ08TB220K	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019
LHLZ08TB9R0M	UTY-DN19-05D	Discontinuation	6/26/2019	9/26/2019