

Product/Process Change Notifications



PCN - 15 127

Release Date: November 25 2015

Product Name:	AirMax Stitched Header 3P, 4P, 5P		
	AirMax Stitched Header 3P, 4P, 5P		
Product Manager:	Talee Luo		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Global		
Type of Change:	Location Change		
Change Description:	By this change, FCI Jurong will act as the backup plating location for FCI Dongguan when there are constraints for plating terminals of Airmax Stitched Header 3P, 4P and 5P.		
Reason for Change:	There has been an increase in customer demand for Airmax Stitched Header 3P, 4P and 5P. FCI Dongguan has limited plating capacity and is constrained by this increase in demand. As a result, we are adding FCI Jurong as a backup plating location. FCI Jurong Plating line has the same plating performance / spec as that of Dongguan and is qualified to plate these terminals since 2012. Adding a back up location would ensure better support for future demand and improve the flexibility on shipment.		
Affected Parts:	10122769-101LF, 10123358-101LF, 10116601-101LF, 10115031-101LF, 10122770-101LF, 10123359-101LF, 10117992-101LF, 10115025-101LF, 10122771-101LF, 10123360-101LF, 10116602-101LF, 10115033-101LF		
Effective Date of Change:	November 28, 2015		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	NA		
Qual/Test Data Attached?	No		
Samples Availability Date:	November	25	2015
Available Alternatives?	No		
Questions?	<i>Contact your local FCI Representative, or Product Manager</i>		
	<i>Luo Talee</i>		
	<i>Talee Luo@fci.com</i>		

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.
 PCN is considered approved by the customer if no communication is received within 3 weeks