

**Product Change Notification:****Reference: PCNMK1004****Affected Part Numbers:**

4600 Series:

46102C	46222C	46472C
46103C	46223C	46473C
46104C	46224C	46474C
46105C	46281C	46541C
46152C	46332C	46682C
46153C	46333C	46683C
46154C	46334C	46684C

**Description of the Change:**

Originally, when looking down on the product from above, the potting 100% filled the visible gap between the core and the outer shield as shown in the following picture:



Now, the gap is only part filled (with the corners excluded), as seen in the picture below:



This change was implemented at the beginning of March 2014.

**Potential Product Performance / Behavior Impact:**

No changes to form, fit, or function as per the datasheet specification.