

Title of Change:	Update to PD24134XA- Reactivation of previously discontinued part BD682G
Last Time Buy Date:	NA
Last Ship Date:	NA
Contact information:	Contact your local onsemi Sales Office
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

onsemi wishes to inform customers of this update to PD24134XA, announcing the reactivation of previously discontinued parts listed in this notice to which shall continue production for at least the next 5 years. The part shall be considered active.

This update notice was issued upon customer's request.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 8685022

USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 337902229

Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ + 81 3 6880 1771

Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Impacted Part	Replacement part	Supplier
BD682G	NA	NA

Appendix A: Changed Products

PCN#: PD24134XA1
Issue Date: Sep 03, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
BD682G			NA	NA